

REPORT ON LENGTHSMAN APRIL/MAY 2020

At the last council meeting it was agreed that defects listed by the Lengthsman's should be reported to the locality steward

To date to my knowledge these defects have not been reported

These being

WUPCC 002

U7028 Near village school

We jetted from both chambers in the footway but failed to get through.

The camera survey shows a complete break in the pipe possibly caused by when an adjacent services trench was excavated.

The area of the break has been marked on the foot way

WUPCC 007

C1280 near A40 junction

The ditch on the near side of the road needs clearing

Request please that locality steward contacts riparian owner to clear this ditch

WUPC 008

C1280 Penyard view area

Roadside ditch needs cleaning between the head walls request that the locality steward contacts the owner to clear this ditch

After consultation with John Smart and Linda Dunn The lengthsman was instructed to do the following work in May

Routine maintenance work

Which includes the following

- 1 Clear grids and clean out road gully's. Jet connecting pipes
- 2 Clear road culverts and jet.
- 3 Check inspection pits.
- 4 Clear ditch headwalls.
- 5 Clear grips and reform leads.
- 6 Clear minor obstruction from ditches and reform leads.
- 7 Clean off road signs.
- 8 Clear minor storm debris off roads

9 Strim round grit bins and road signs.

10 Strim verges on bends junction splays and areas regularly used by pedestrians and no footway is present.

Work as shown on attached map