

Report on lengthsman March 2020

The lengthsman did a 1 day maintenance inspection of some of the Parish

This included inspection and clearing of grips and catch pits

A defect report was generated by the lengthsman and submitted to council this report was distributed before our last meeting

At our last meeting it was decided that the lengthsman should do a further 2 days work.

I as instructed generated a list of work that needed to be done and sent this to Nick our Clerk.

The lengthsman was sent the following

"If at all possible we would like to have two further maintenance days in March to cover the following:

1 complete maintenance work not done on the first day inspection of drainage gulleys catch pits and grips .

2 Clear side walks on both side of A 40 from the Weston Cross Inn to Weston Park

3 Clear the pavement on the raised bank on the southside of Church Road (the road opposite the Weston Cross inn) from the A40 to the end of the White House.

4 Defects listed as WUPCC002 , WUPCC 003 and WUPCC 004 as listed on the February 2020 defects List

Could you also please quote for the clearing of the remainder of the raised pavement in church lane from the white house to the Church ?

Also we are intending to have some road sign names on the roads in the village that run off the A40. I think there are around five roads in all that signs are needed for. We have asked Balfour Beatty for a quote for the signs but is this something you could quote for please both the signs and installation ? I think they will be stand alone road name signs.

A further 2days work was done by the lengthsman

And the Defect Report. titled

March 2020. Follows

WUPPC 006.

C1283.

Kingstone.

The road gullies on the approach road from Weston have been cleared and are running with the exception of one near Kingstone Barns.

Action-we need to spend mor time in the area to locate chambers in the verge so we can jet the main drainage pipe and clear the blockage.

WUPPC 007.

C1280.

Near A40 junction.

The ditch on the nearside of the road needs clearing to the gully headwall.

Also, the road gulley needs jetting when we find the chamber on the opposite side of the road.

Action-Request Locality Steward to contact Riparian Owner and arrange for ditch to be cleared.

WUPPC 008.

C1280.

Penyard View Area.

Roadside ditch opposite the property needs clearing between the headwalls.

Action- Request Locality Steward to contact the Riparian Owner and arrange for the ditch to be cleared.

RECORD OF WORKS CARRIED OUT BY TERRY GRIFFITHS CONTRACTS

PARISH COUNCIL

Weston under Penyard Parish Council.

ACCOUNT

Roads.

MONTH

March 2020 (1). Green

INVOICE NO.

Description of work carried out: -

Specific Task Work.

WUPPC 002.

U70208.

Near village school.

We jetted from both chambers in the footway but failed to get through.

The camera survey shows a complete break in the pipe possibly caused by when an adjacent services trench was excavated.

The area of the break has been marked on the footway.

Action-notify Locality Steward.

WUPPC 004.

C1275.

Frogmore Area.

We located the first section of the drainage system in the area -3road gullies, two chamber and the outfall pipe for that system in adjacent scrub land.

These were all cleared and partially flushed through with what water we had left in the jetter.

Action- revisit to complete flush jetting and a small amount of digger work to excavate a short length of ditch to allow water to flow into a watercourse.

Roads covered on this visit.

C1280.

From A40 to C1283.

C1283.

To parish boundary

WORK REQUIRED TO BE DONE NEXT MONTH

Complete clearing the paths on the A40 as previously requested

Further ongoing routine maintenance to storm water drainage

Routine Maintenance Workforce the lengthsman is required to do as below

1Clear grids and clean out road gully's.

Jet connecting pipes.

2 Clear road culverts and jet.

3Check inspection pits.

4 Clear ditch headwalls.

5 Clear grips and reform leads.

6 Clear minor obstruction from ditches and reform leads.

7 Clean off road signs.

8 Clear minor storm debris off roads.

9 Strim round grit bins and road signs.

10 Strim verges on bends junction splays and areas regularly used by pedestrians and no footway is present.