

Lengthsman Outstanding Work revision !

Report Number	Defect	Date reported	Action required	Action Taken
WUPCC 001	U70205 junction A40-3gulley blocked	February 2020	lengthsman to be instructed to clear	none
WUPCC 002	U70208 camera survey shows break in pipe position marked on footpath	March 2020	Notify locality steward	none
WUPCC 003	C1275 Pontshill village sign-connecting pipes need jetting	February 2020	lengthsman to be instructed to clear	none
WUPCC 004	C1275 Frogmore area drains and outlet cleared and partially flushed Drains located but need flushing	March 2020	Lengthsman to complete	none
WUPCC 005	U70207 JUNCTION with A40 road gulley not draining	February 2020	lengthsman to be instructed to clear	none
WUPCC 006	U70210 short stretch of ditch needs cleaning	February 2020	lengthsman to be instructed to clear	none
WUPCC 006B	Kingstoneb -Road gullies cleanedwith one exception.need to locate chambers and jetmain drainage pipe		lengthsman to be instructed to clear	none
WUPCC 007	Near A40 junction.ditch on roadside needs clearing to gulley headwall Road gulley needs jetting	March2020	Locality steward to contact riparian for ditch to be cleared	none
WUPCC 008	C1289 Penyard view area Roadside ditch needs clearing	March 2020	Locality steward to contact riparian for ditch to be cleared	none